



Notes:

1. The vertical foundation error is $\leq 5\text{mm}$
2. The location of the control box can be interchangeable.